



2040-80

RECESSED SELF-LUMINOUS EXIT SIGN

INSTALLATION AND OPERATING INSTRUCTION

IMPORTANT NOTICE REGARDING FEDERAL REGULATORY COMPLIANCE FOR SELF-LUMINOUS SIGN ORDERS

Per 10 CFR 32.52 – U.S. Nuclear Regulatory Commission Requirements

Federal regulations require us to collect and report the information requested on this form for every self-luminous sign we ship. To ensure full compliance with 10 CFR 32.52, the information must be provided before your order can be released to production.

IMPORTANT NOTES:

- This information is **required by regulation** and is not optional.
- The **responsible party cannot be a contractor, installer, or electrician**. It must be someone employed by the entity that operates or owns the installation location.
- **Signs cannot be installed in temporary structures** such as job site trailers or used for temporary applications.

REMOVAL INSTRUCTIONS

Slide the sign sideways (either to the left or right) by pushing or tapping the frame lightly with a non-metal hammer. Pressure needs to be applied to the end of the sign at approximately 0.5" (12 mm) below the center line of the sign. The sign will meet resistance after it has moved approximately 3.0" (75 mm). The back edge of the sign has come into contact with the end of the wall-mounting bracket. Pull the end of the sign you are pushing 0.125" (3 mm) away from the wall.

CAUTION: The sign will release from the wall without warning and must be held securely while continuing to slide it sideways.


Continue to slide the sign another 3.0" (75 mm) in the same direction to release it from the wall completely.

SAVE THESE INSTRUCTIONS

31 Waterloo Ave • Berwyn, Pa • 19312 U.S.A
Telephone: (610) 647-8200 • Email: support@isolite.com

INSTALLATION INSTRUCTIONS

- 1. Cut a rectangular hole in the wall 8.375" high and 12.875" long, and at least 3.0" deep. Be careful not to cut hole too big or there will not be enough material to secure screws.
- 2. Peel the protective film from both sides of the polycarbonate faceplate.
- 3. Insert metal tray into wall, insert the EXIT sign assembly into the tray, lay the polycarbonate faceplate over the assembly, then secure everything at once using the four (4) provided screws.



SAVE THESE INSTRUCTIONS

31 Waterloo Ave • Berwyn, PA • 19312 U.S.A
Telephone: (610) 647-8200 • Email: support@isolite.com